# FRAZIER PARK PUBLIC UTILITY DISTRICT

#### MANAGERS REPORT

For the month of February 2021

## Prepared by:

Jonnie Allison, General Manager

Frazier Park Public Utility District

#### **INFORMATIONAL ITEMS**

#### I. WATER REPORT

Water Pumped this month 964,700 Cubic Ft.

Water sold: 523,090 Cubic Ft.

Water used for Fire & Flushing Line: 67,529 Cubic Ft.

Lag Differential: 38.47%

Water Loss: 371,081 Cubic Feet

Average chlorine residual: 1.01 MG/L

#### II. MAINTENANCE AND REPAIR: February 2021

Description	Current Month	rent Month Last Mo.	
METER CHANGES	0	0	2
AFTER HOUR CALL OUTS	26	13	39
MAIN LINE LEAK REPAIRS	1	5	6
USA LOCATES	8	0	8
SERVICE/WORK ORDERS	243	217	246
CUSTOMER "TURN-ONS"	0	1	1
CUSTOMER "TURN-OFFS"	2	2	4
LOCK OFF (NON PAYMENT)	0	0	0
SERVICE RECONNECT	0	0	0
SHUT OFF NOTICES	0	0	0
GALLONS CL2 USED	130	143	273
WATER QUALITY COMPLAINTS	0	0	0

#### **III.** WATER QUALITY COMPLAINTS:

#### IV. ISSUES AND ACTIONS:

There was (1) mainline break(s) / repair(s) in the month of February 2021

Location	Dates	Comments
Elm & Locust	02/02/21	8" Steel Pipe

Nine (9) routine bacteriological samples were completed in compliance with the California Department of Public Health water quality regulations: Four (4) samples within the distribution system, and five (5) more at our wells and springs. Both Sam Young & Pine Canyon Springs are isolated from the system.

■ There were (26) after hour callout(s) in the month of February 2021

		Comments
Location	Dates	Comments
Wolfe Tank	02/04/21	Booster 1 Failure
Wolfe Tank	02/04/21	Tank Overflowed
Wolfe Tank	02/05/21	Booster 1 Failure
Well 5	02/05/21	Booster 1 Failure
Elm Tank	02/05/21	BWP 2 Booster Installation
Summit Trail	02/06/21	Water on Summit. Leak from Wolfe Tank
Pine 2 PLC	02/06/21	Communication Failure
3809 Arroyo Trail	02/14/21	Report of no water. Customer informed they needed to call plumber
Corporate Yard	02/18/21	M & S Security Burglar Alarm No sign of intrusion.
Well 6	02/18/21	Well Failure. Reset SCADA and returned to service.
Elm Tank	02/18/21	Booster 1 Failure
Harrison Tank	02/18/21	Booster 1 Failure
Well 6	02/18/21	Well Failure. Reset SCADA and returned to service.
Well 5	02/20/21	Communication Failure
Well 6	02/20/21	Well 5 Booster 2 Failure. Reset SCADA and returned to service
Harrison Tank	02/20/21	Communication Failure
Forestry Tank	02/20/21	PLC Failure
Well 6	02/22/21	Well Failure. Reset SCADA and returned to service
Well 5	02/23/21	Well Failure. Reset SCADA and returned to service
Hale & Mead Trail	02/26/21	Water Leak
Parcel B	02/26/21	PLC Communication Failure
Well 6	02/27/21	Well Failure. Reset SCADA and returned to service
Parcel B	02/27/21	PLC Communication Failure

## V. <u>NEW SERVICES INSTALLED:</u> (0)

Address	Lot / Block / Tract	Size

### VI. <u>NEW BUSINESS:</u>

■ APPLICATIONS FOR WATER SERVICE – 0